Customer CU-DAR001 Dart Helicopters Services Drawing Name SPACER	Date: F User K	riday, 11/16/2007 7:21:22 AM im Johnston 21.33	Process Sheet	<u></u>	
P.O. Number : ALIA		: 35814	Drawing Name	: SPACER	
Comment SECOND CHECK SECOND CHEC	P.O. Number This Issue Prsht Rev. First Issue Previous Run	: NA : : NA : : MA : : MACHINED P	Drawing Number Project Number ARTS Drawing Revision Material	: D3681 REV A : N/A : A : A	70 60 Um: Each
Seq. #: Machine Or Operation: Description :		: Est Rev A new issue 07-10-3	_		
Seq.#: Machine Or Operation: Description:	Additional Prod	uct			
Comment: Qty.: 0,9807 f(s)/Unit Total: 1,8896 f(s) Material: (M6061T6T0.313W.058) Batch 1/2 (106 3-7) 2.0 HARDINGE HARDINGE GNC LATHE SMALL Comment: 1.TURN AS PER FOLIO FA711& DWG D3681 FOLIO REV: DWG REV: DWG REV: 1. 2-DEBURR AS REQUIRED Comment: INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE Comment: SECOND CHECK Comment: SECOND CHECK DATE OF MACHINE Comment: PACKAGING 1 PACKAGING RESOURCE #1	Job Number:				.*
Comment: Qty.: 0,9807 f(s)/Unit Total: 1,8896 f(s) Material: (M6061T6T0.313W.058) Batch 1/2 (106 3-7) 2.0 HARDINGE HARDINGE GNC LATHE SMALL Comment: 1.TURN AS PER FOLIO FA711& DWG D3681 FOLIO REV: DWG REV: DWG REV: 1. 2-DEBURR AS REQUIRED Comment: INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE Comment: SECOND CHECK Comment: SECOND CHECK DATE OF MACHINE Comment: PACKAGING 1 PACKAGING RESOURCE #1	Seq. #:		Description :		
Material: (M6061T6T0.313W 058) Batch 10 0 347 2.0 HARDINGE HARDINGE ONG LATHE SMALL Comment: 1TURN AS PER FOLIO FA711& DWG D3681 FOLIO REV: DWG REV: DWG REV: 1		· · · · · · · · · · · · · · · · · · ·			
(M6061T6T0.313W.058) Batch 1/1 06 34 7 20 HARDINGE HARDINGE CNC LATHE SMALL Comment: 1TURN AS PER FOLIO FA711& DWG D3681 FOLIO REV: DWG REV: DWG REV: 1	Com	ment: Qty.: 0.0307 f(s)/Unit Total: 1	.8896 f(s)	1180111011101	
Batch M 106 347 20 HARDINGE HARDINGE CINC LATHE SMALL Comment: 1. TURN AS PER FOLIO FA7118 DWG D3681 FOLIO REV: DWG REV: 2-DEBURR AS REQUIRED 2-DEBURR AS REQUIRED NSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 SECOND CHECK Comment: SECOND CHECK F. 07/1//27 TO Comment: PACKAGING 1 PACKAGING RESOURCE #1					
Comment: 1-TURN AS PER FOLIO FA711& DWG D3681 FOLIO REV: DWG REV: 2-DEBURR AS REQUIRED 2-DEBURR AS REQUIRED INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 SECOND CHECK Comment: SECOND CHECK DATE OF MACHINE Comment: PACKAGING 1 PACKAGING RESOURCE #1		Batch: <u>W 1 06 34</u> 7	20 on /u /27		
FOLIO REV:	2.0	HARDINGE	HARDINGE CNC LATHE SMAĽL		
Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 Comment: SECOND CHECK DATE OF ACKAGING 1 PACKAGING RESOURCE #1	Com	FOLIO REV:	G D3681		
Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 SECOND CHECK Comment: SECOND CHECK 5.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1		2-DEBURR AS REQUIRED		7	
Comment: SECOND CHECK 5.0 PACKAGING 1 PACKAGING RESOURCE #1	3.0	QC2	INSPECT PARTS AS THEY COME	OFF MACHINE	- 6
Comment: SECOND CHECK 5.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1		the second secon		n/11/27	(10)
5.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1	4.0	QC8	SECOND CHECK		
Comment: PACKAGING RESOURCE #1	· · · · · · · · · · · · · · · · · · ·			. 07/1/27	(70)
	5.0	PACKAGING 1	PACKAGING RESOURCE #1		
Identify and Stock Location: LG 8F 07/11/28	Com		, ,		
		Identify and Stock Location: 2	07/11/28		

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	:						
·							4
							4

Part No: _	PAR #:	Fault Category:	NCR: Yes No DQA:	Date: <u>0/11/08</u>
			QA: N/C Closed:	Date:

NCR:			WORK ORDER NON-CONFORMANCE (NCR)					
		Description of NC		Corrective Action Section E	3	Verification	A	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
						1		
		·						

NOTE: Date & initial all entries

Date:

Friday, 11/16/2007 7:21:23 AM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SPACER

Job Number: 35814

Part Number: D36811

Job Number:

Seq. #:



Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



h Still-28

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




Dart Aerospace Ltd

		-T	1 -	
Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				-
	,			MA USA
				E
				Prod Mgr

Part No:	PAR #:	_ Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	Closed:	Date:

NCR:			WORK ORDER NON-CONFORMANCE (NCR)				WORK ORDER NON-CONFORMANCE (NCR)				
		Description of NC		Corrective Action Section B		Verification	A I				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Action Description Sign &		Approval Chief Eng	Approval QC Inspector			

NOTE: Date & initial all entries



					Work Ordon	
DART AEROS	PACE LTD				Work Order:	
Description:					Part Number:	D3681-1
Inspection Dwg:	Rev:	A				Page 1 of 1
		7				
	FIRST	ARTICLE IN	_	ON CHE		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
-3/3	+/010	.313				
	+1010	.197				
.197 4.080	+/010 + .030 +/010	4.095				
1005 x45°	+1010	.027845	Ö			- page 10
						· J. January
470						
\$3.5						
	AMPIN TO THE RESERVE					
				<u>-</u>		
						, AM. 0
5						
)						
			-			·
Measured by: &	P , A	Audited by:	F.F.		ototype Approv	val:
Date:	1/11/27	Date: 👌	7/11/27	7	Da	ite:

Revised by	Approved
KJ/JLM	<u> </u>
	1.4.4
	,
	\ \lambda

Change New Issue

Date

Rev